
Fig. 1






Fig. 2

Fig. 3






Fig. 4




5/9


Fig. 5

(a) (b)





(c) (d)






Fig. 6




Fig. 7




Fig. 8




Fig. 9

| | | 90 | 02 90 | 906 |
|-------------------|---------------------------|-------|---------|----------|
| | | left | right / | overall/ |
| 908 910 912 | - fracture detection rate | 80.0% | 84.6% | 82.6% |
| | false alarm rate | 15.2% | 19.5% | 17.6% |
| | - classification accuracy | 78.8% | 75.6% | 77.0% |




Fig. 10




Fig. 11